



Boeying	Thread	HydraForce	Danfoss	Eaton-Vickers	Command Controls [Bucher]	VIS	Argo-Hytos	SUN
C04-3	7/16-20		CP04-3		C0430	VH 131		
ZP-43		VC04-B3						
C08-2	3/4-16	VC08-2	SD C08-2	C-8-2	C0820	SAE08	A2	
C08-3		VC08-3	SD C08-3	C-8-3	C0830	SAE08-2	A3	
C08-4		VC08-4	SD C08-4	C-8-4	C0840	SAE08-3	A4	
S08-3						VH 102		
D08-4						VH 081		
C10-2		7/8-14	VC10-2	SD C10-2	C-10-2	C1020	SAE10	B2
C10-3	VC10-3		SD C10-3	C-10-3	C1030	SAE10-2	B3	
C10-4	VC10-4		SD C10-4	C-10-4	C1040		B4	
C10-5	VC10-5							
C10S-2								
C10S-3								
C10-3S						C1025		
C10-3L				CP10-3L				
S10S-3								
D10S-4								
C12-2	1 1/16-12		VC12-2	SD C12-2	C-12-2		SAE12	
C12-3		VC12-3		C-12-3				
C12-4		VC12-4		C-12-4				
C12-S5		VC12-S5						
C16-2	1 5/16-12	VC16-2	SD C16-2	C-16-2	C1620	SAE16		
C16-3		VC16-3	SD C16-3	C-16-3	C1630			
C16-4		VC16-4	SD C16-4	C-16-4	C1640			
M12-2	M12x1						QC2	
M22-3	M22x1.5					VH 080		
M27-3	M27x1.5			A12336			R3	
T06-2A	G1/4					VH 007		
T10-2A	G3/8					VH 008		
T12-2A	G1/2					VH 009		
T16-2A	G3/4					VH 057		
ZP-23	G1/8							
T-13A	M20x1.5							T-13A
T-5A	1-14UNS							T-5A
T-16A	M36x2							T-16A
T-11A	M20x1.5							T-11A
T-2A	1-14UNS							T-2A
T-17A	M36x2							T-17A